

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

RUIN 5MT1805

HABS CO-211

(Broken Beam)

Approximately 1 mile North of County Road G

Cortez vicinity

Montezuma County

Colorado

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Lisa Lynch, photographer, November 2008

CO-211-1	Perspective view from above site looking to the northwest
CO-211-2	Exterior walls of Rooms 8 and 9 looking to the north/northwest
CO-211-3	Wall south of Room 8 looking to the west
CO-211-4	Interior walls of Room 9 and wall south of Room 8 looking to the east
CO-211-5	Interior walls of Room 9 looking to the east
CO-211-6	Exterior of east all of Room 9 looking west
CO-211-7	Perspective view of Rooms 3, 4, 5, and 6 looking to the west/northwest
CO-211-8	Interior walls of Kiva 1 looking east
CO-211-9	Rock art on cliff face in Room 2 looking to the north
CO-211-10	Interior of west wall of Room 4 looking to the east
CO-211-11	Perspective view from west end of site looking to the east